

Car Safety Inspection Certificate

U. R. 917

STATE OF COLORADO
DEPARTMENT OF REVENUE
MOTOR VEHICLE DIVISION
ROOM 40, STATE CAPITOL BUILDING DENVER

SAFETY INSPECTION CERTIFICATE

REG. NO. 29908	LICENSE NO. 8-677
YEAR MFD. 1946	MAKE Nash
MOTOR NO. 406905	MILEAGE 2500
NAME OF OWNER Sam Mc Mullin	
OWNER'S ADDRESS 27 Grand	
OPERATOR'S I. L. C. 8-137 DATE 8-13-46	
OWNER'S L. C. NO. 8-137	
BRAKE SYSTEM <input checked="" type="checkbox"/> OK <input type="checkbox"/> REPAIR	REARVIEW MIRROR <input checked="" type="checkbox"/> OK <input type="checkbox"/> REPAIR
LIGHT SYSTEM <input checked="" type="checkbox"/> OK	HORN <input checked="" type="checkbox"/> OK
EXHAUST SYSTEM <input checked="" type="checkbox"/> OK	REAR WINDOW <input checked="" type="checkbox"/> OK
STEERING SYSTEM <input checked="" type="checkbox"/> OK	REFLECTOR <input checked="" type="checkbox"/> OK
WHEEL ALIGNMENT <input checked="" type="checkbox"/> OK	BUFF. FR. <input checked="" type="checkbox"/> OK
WINDSHIELD <input checked="" type="checkbox"/> OK	FLASH, FLARES, PUPPET <input checked="" type="checkbox"/> OK
WINDSHIELD WIPER <input checked="" type="checkbox"/> OK	REQUIRED TRUCK LAMP <input checked="" type="checkbox"/> OK

I personally have inspected the above described vehicle as (State)
and found it to be in good condition and safe for use on the public roads.
SALES TAX, FEE, etc. 7.00

Phone 94 743 N. First St.
FIRM NAME GRAND JUNCTION, COLORADO
ADDRESS
INSPECTION STATION NUMBER

IDENTIFIER

2011.8.28

ARTIST

Sam McMullin [1866 - 1946]